

Inspection No. 141126-115

Visual Property Inspection

119 Craven Rd Toronto, ON M4L 2Z4

Prepared for :

The Weir Team

Phone No. : (416) 465-4545



Inspected by :

Allen Ottaway 160 Goodman Dr. Oshawa, Ontario L1J 7V8 Phone: (289) 240-1189 Email: allen.ottaway@pillartopost.com

Report Commentary



Date: 04-Jan-2016

119 Craven Rd, Toronto, ON M4L 2Z4

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the entire report.

1.0 <u>Exterior</u>

1.1 Window Exterior

Further investigate extent of window frame rot and replace as required. Window frame at the rear of the house shows substantial rot/deterioration.

2.0 Roof Structure

2.1 Covering

Roof was recently recovered with a new membrane.

2.2 Sec. Roof Life Expectancy

Roof over porch was recently re-shingled.

3.0 <u>Electrical Service</u>

3.1 Service Size

200 amp service, copper wire.

3.2 Circuit Wires/Receptacles

Install GFCI receptacle on the exterior of the home to promote safety. The current receptacle is not GFCI and it also has the hot and neutral wires reversed.

4.0 <u>Heating</u>

4.1 Heating System

Mid efficiency furnace is 8 years old. Typical life expectancy is 20 years. Functioning as intended at time of inspection.

5.0 <u>Plumbing Components</u>

5.1 Hot Water Tank

Hot water on demand system is 5 years old. Functioning as intended at time of inspection. See additional information at the end of the report.

6.0 Interior Living Spaces

6.1 Railing

Install handrail to promote safety



	te: 04-Jan-2016		119 Craven Rd, Toronto, ON M4L 2Z4
			Property and Site
Limitations Uegetation/Tree/Shrub Snow/Ice Cover AGE OF HOME 75+	Vines	Debris/Ob	struction
Conditions ✓ Sunny/Mostly Sunny ☐ Snow/Ice Conditions Approx. Temperature -15 celsit	Cloudy/Most	ly Cloudy	Rain/Wet Conditions
Building ✓2 Story Duplex	Condo	Townhome	
•			² 15 feet of all bedrooms for occupant safety.
sinks, and storage iter		oxes, appliances,	clothes, items stored under some or all
regularly over time, ar			unty, can vary significantly and change
	ode inspection. Local c		
regularly over time, ar Landscaping	code inspection. Local co nd are not a part of this h	nome inspection.	
regularly over time, ar Landscaping Bushes/Hedge/Flower Bed Front Porch Crack Front Porch Light	code inspection. Local co ad are not a part of this h Vine	Slopes To	House Brick/Block/Paving Stone Operational
regularly over time, ar Landscaping Bushes/Hedge/Flower Bed Front Porch Crack Front Porch Light	code inspection. Local co nd are not a part of this h	Slopes To	House
regularly over time, ar Landscaping Bushes/Hedge/Flower Bed Front Porch Crack Front Porch Light	code inspection. Local co ad are not a part of this h Vine	Slopes To ☐ Concrete ✓ Representa	House Brick/Block/Paving Stone Operational
regularly over time, ar Landscaping Bushes/Hedge/Flower Bed Front Porch Crack ✓ Wood/0 Front Porch Light Unsecured Appear Deck(s)/Patio(s) Slopes to House	code inspection. Local co ad are not a part of this h Uvine Composite s to be sensor activated	nome inspection.	House Brick/Block/Paving Stone Operational tive # Inspected/Tested



Date: 04-Jan-2016		119 Craven Rd, Toronto, ON M4L 2Z	
			Exterio
Limitations			
Insulation Conceals	Clearance	Debris/Obstr	uction
✓ Obstructed/No or Partial Access	Bushes/Vin	es/Tree Obstructions	Snow/Ice Cover
Foundation Wall			
Stone/Flagstone	Brick	Concrete	Block
Preserved Wood	Partially Co	oncealed	Hairline Cracking-typical
Completely Concealed			
Siding conceals the under	side of the home	e. Not able to deter	mine what the foundation is comprised of.
Exterior Walls			
Wood/Composite	Stucco	Vinyl/Alumi	num Brick/Stone
On Wood Framing			
Ensure proper caulking and dissimilar materials junction		all required locations	s and junctions such as windows, doors,
Repair siding to prevent wat	er and pests per	netrating and related	damages.
Window Exterior			
✓ Wood	Vinyl	Wood Int/Vir	nyl or Metal Cla
Further investigate extent o house shows substantial rot		rot and replace as r	equired. Window frame at the rear of the
Maintain wood windows/trim	work to reduce	deterioration	
Garage Side or Back Door			Operational
Dented/Minor Damage	Binds - Adj	ust/repair	
Exterior Lighting			Operational

✓ Not all lights tested

Unsecured - repair

Operational Representative # Inspected/Tested



	Date: 04-Ja	an-2016		119 Craven Rd, Toronto, ON M4L 2Z4
				Roof Structure
Inspected By: Binocular	Roof Edge	✓ Walk On	No Access	
Limitations	Solar Panels	Gravel Cover	☐ Steep Slope ☐ Material Too S	☐ Height lippery
Main Roof Flat Estimated Age 10 +	Gable - years	Hip/Valley	Shed	
Gutter/Downsp Galvanized Above Ground D Clean and	Plastic Discharge	✓ Aluminum	Copper	Below Ground Discharge
Covering Concrete/Clay T Metal	Other	─ Wood Shingle/ ▼ Flat Roof Men	ıbrane	Asphalt/Composite Shingle
Roof was re	ecently recovered	with a new memb	rane.	
Life Expectanc ✓ Typical	y ∏Middle	End	Exceeded	
Accessory Vent Stack	Solar Panels	Skylight(s)	✓ Vent Caps	
Flashing Not Checked/Co Roof to Wall Aluminum/Galva	Stack	Chimney Valley Tarring/Conce	Drip Edge Roll Roofing aled	☐ Flat Roof ☐ Skylight ✓ Replace When Re-roofing
Chimney/Vent Wood Brick/Block/Stor	▼ Metal	Furnace/Water	Heater	Fireplace
Sec. Roof Life	Expectancy Middle	End	Exceeded	

Roof over porch was recently re-shingled.



	Date: 04-Ja	un-2016		119 Craven	Rd, Toronto, ON M4L 2Z4
					Electrical Service
Service Entra	ance				
□No Conduit	Overhead	Underground	✓ 120/240V		
Entrance Cal	ble				
Concealed	Aluminum	Copper			
Main Disconi	nect				
Switch/Cartrie	dge Fuse	Breaker			
Service Size					
Have Electric Amps 200	ian Evaluate				
200 amp	service, copper wire).			
Distribution I	Non Standard In	nstallation	Obstructed		
Panel Rating					
Room For Exp Amps 200	pansion				
Fuse					
Breaker	GFCI Breaker	AFCI Breaker	Over-Fused	Cartridge	Glass
Circuit Wires	/Receptacles				
Aluminum	Copper	Representative	# of Outlets Inspect	ed/Test&dvitched Out	tlets
	-CI receptacle on the to has the hot and ne			fety. The current	receptacle is not GFCI
Grounding					
✓ Concealed	Ground Rod	Water Main			



				Heating
Data Plate	Incomplete			
Model: Gama		BTU Input: 50000	Estimated	Age: 8 years
Limitations				
System Operation	ng In AC Mode	System Shut Do	wn/Not Tested	
Smoke Detect	ors			
Basement	✓ 1st Floor	2nd Floor	3rd Floor	
Thermostat/Hu	umidistat			Operational
Unsecured	✓ Programmable	Standard		
Heat Type				
Convector - Wa Radiant - In-Flo		Forced Air	Radiator/Baseboard	
Burner Type				
Conventional	Mid Efficiency	High Efficiency		
Heating Fuel S				
Gas	Electric	Propane		
Fuel Source S ✓ Beside	hut Off Location			
Heating System	m			Operational
Advise Service	Repair Contract	Verify Service I	list w/Selle	
Mid efficier of inspection	ncy furnace is 8 yea on.	ars old. Typical lii	e expectancy is 20 years. Fi	unctioning as intended at time
Fresh Air Sup	ply			
✓ Internal	External			
Venting				
✓ Metal	Corrosion	Sidewall/Plastic		
Consult a c	qualified technician	to determine if cur	rent vent material is rated for	current application.
Life Expectance	су			
✓ Typical	Middle	Exceeded	Middle/End	
Gas Burner				Operational
Not Checked				



Date:	04-Jan-2016
-------	-------------

					Heating
Ignition					
✓ Electronic	Pilot & Thern	nocoupl			
Heat Shield					
Missing	Corrosion	Soot	None		
Burn Chamber	r				
Advise Adjustm	nent	Soot			
Motor/Blower					Operational
Direct Drive	Noisy	Other			
Filter					
✓ Disposable	Missing	Inoperable	Undersized	Damaged	
Duct/Joint/Hou	using				
Unsecured	Corrosion				
Cooling Fuel S	Source				



Plumbing	Components
----------	------------

Limitation Finished Basem	nent	Private System	1		
Public Supply ✓ Concealed □ Not Metered	Lead	Galvanized	Plastic	Copper	Metered
Public Shut-Of	ff Valve	Tagged/Labele	ed for Convenience		
Water Pressur	e ✓ Typical	High			
Water Quality	Debris	Odor	Advise Well V	Vater Quality Tes	✓ Typical
Distribution Pi	iping ✓ Plastic	Galvanized	Copper		
Cross Connec	tion Laundry	Hose Bibb	▼ None Visible		
Waste Drainag	Je Cast Iron	✓ Plastic	Copper	Pump/Inspect	Septic System
Main Cleanout	t				
Hot Water Tan		Gas		Some Corrosi	Operational ion Noted - Typical
Hot water	-				pection. See additiona
Life Expectance	Cy Exceeded	Middle	Middle/End		
Fuel Shut-Off Concealed Location beside					
Discharge Tub	Discharge				



	Date: 04	119 Craven Rd, Toronto, ON M4L 2Z4				
				Plu	umbing Com	ponents
Venting	✓ Sidewall	Improper Rise	Unsecured	Corrosion	Soot	
Burn Chambe	r	tment				



	Date: 04-Jan-2016		119 Craven Rd, Toronto, ON M4L 2		
					All Baths
Location Basement	✓ 1st Floor	2nd Floor	3rd Floor		
Water Flow ✓ Normal	Suspect				
Floor Worn	Minor Cracking	g - Typica	Stains/Minor Da	image	
Regrout floo	or tiles to prevent	water penetration a	and related damage	es.	
Wall Uneven	Patched - Typic	al	Ceramic		
Ceiling Uneven	Minor Patching	- Typical	Minor Cracking	- Typica	
Door Binds - Adjust/R	epair	Damaged	Representative #	# Inspected/Tested	Operational
Lighting	Unsecured				Operational
Exhaust Fan	on	Dirty - Clean fo	r best function	Noisy - Servic	Operational e/Repair/Replace
Sink Worn	Chip/Scratch	✓ Solid/Granite			
Faucet	Unsecured	Corrosion	Minor Leakage	at Handle - Repair	Operational
Trap/Drain	nnected/inoperable-	RepaisfowcDnaimie61	æan/Repair	Corrosion - M	onitor for leaks
Vanity Worn/Scratches	Missing/Loose	Hardware	Prior Stains-No	Leakage Now	
Toilet No Shut-Off Secure toile	✓ Unsecured et to reduce secon	Crooked - Moni	-		Operational



	Date: 04	119 Craven F	Rd, Toronto, ON M4L 2Z4		
					All Baths
Tub/Enclosur	6				
Ceramic/Tile	Solid Surface/	Marble	Fiberglass	Plastic Panels	
Minor Mildew	Stains-Treat/Clean	Worn - Scrat	cches/Chips		
Tub Faucet/M	ixer				Operational
Not Tested	Unsecured	Leaky-Secur	e/Repair/Replace		
Shower Head					Operational
Not Tested	Unsecured	Leaky-Secur	e/Repair/Replace		
Heat Source					
None	Thermostat	Electric	✓ Air Register	Radiant	
Radiator/Convo	ector		-		



	Date: 04-Ja	an-2016		119 Craven Rd, Toronto, ON M4L 2Z4		
				Kitc	hen	
Floor Worn	Minor Cracking	g - Typica	Stains/Minor D	Damage		
Wall Uneven	Patched	Minor Crackin	g - Typica			
Ceiling	Patched- Typic	al	Minor Cracking	g - Typica		
Window Binds - Adjust Treat Wood To	/Repair o Preserve/Protect	Not Tested✓ Representative	Thermal Pane # Inspected/Tested	Operational Single Pane Storm Window		
Lighting	Unsecured	✓ Representative	# Inspected/Tested	Operational		
Sink Worn	Chip/Scratch					
Faucet No Shut-Off Valve Consult plumber to repair act		✓ Unsecured tive leak under sink	Corrosion	Operational Minor Leakage at Handle - Repair ges form water.		
Trap/Drain Slow Drain - Clean/Repair		Corrosion - Mo	onitor for Leakage			
Counter		plash	Minor Damage	/Scratches/Worn		
Cabinet Worn/Scratche	28	Missing/Loose	Hardware	Representative # Inspected/Tested		
Range Hood Cooktop Exhar	ust	□No Exhaust	□ No Light	Operational		
Exhaust vent	Ductless	Concealed	To Exterior			
Filter Missing - Insta	Ill for safety	Unsecured	Damaged	Greasy		
Major Appliar	nces (Built-in)					



119 Craven Rd, Toronto, ON M4L 2Z4

Operational

Operational

Kitchen

All appliances were turned on using regular operating controls if they are connected or not shut down. All functions and different systems are not tested. The test simply comprises turning the appliances on to verify some basic functionality.

Stove/Cooktop

Brand Ikea # 1407470351348

Refrigerator

Heat Source				
None	Thermostat	Electric	✓ Air Register	Radiant
Radiator/Con	vector			



	Date: 04-J	Date: 04-Jan-2016		119 Craven Rd, Toronto, ON M4L 22		
				Ir	nterior Living Spaces	
Floor Worn	Minor Crackin	g - Typica	Staining/Minor	Damage		
Wall □ Uneven ✓ Wood Frame v			Minor Cracking	s - Typica		
Ceiling □Uneven ✓Wood Frame	Patched - Typi w/drywall/plaster	cal	Minor Cracking	- Typica		
Window Binds - Adjust	t/Repair o Preserve/Protect	Not Tested ✓ Representati	Fixed Pane ve # Inspected/Tested	Single Pane	Operational ✓ Thermal Pane	
Lighting	Unsecured	Representati	ve # Inspected/Tested		Operational	
Ceiling Fan	Unsecured				Operational	
Interior Doors	/Repair	☐Hinged ✔Representati	Closet door off ve # Inspected/Tested	track	Operational	
Stairway ✓ Carpet	Wood	Worn	Squeaks - Typic	cal		
Railing Wood/Metal	Incomplete	✓ None				
Exterior Door		Weather Stri	ipping Missing/Improper	Dead Bolt	Operational	
Heat Source	Electric Electric	Radiator/Co	nvector	None		



119 Craven Rd, Toronto, ON M4L 2Z4

Additional Comments

General Comments

This is a Prelisting Inspection performed for the seller of the home in preparation for putting the home on the market for sale. This inspection is completed to ASHI and OAHI standards, is visual in nature, and does not address building code compliance issues which are the purview of municipal building inspectors.




Property and Site Retaining Wall



Retaining wall leaning slightly

Exterior Exterior Walls



Damaged siding



119 Craven Rd, Toronto, ON M4L 2Z4

Exterior Window Exterior



OT/DAT/2016 16:14

Paint wood trim

Electrical Service



200 Amp electrical panel

Rotted window frame



119 Craven Rd, Toronto, ON M4L 2Z4

Heating Heating System



Furnace Plumbing Components Hot Water Tank



Tank less hot water system



119 Craven Rd, Toronto, ON M4L 2Z4

Interior Living Spaces

Railing



Missing handrail

Ground Fault Circuit Interrupter

A ground fault circuit interrupter, or GFCI, is an inexpensive electrical safety device that can protect you and your family members from a serious electric shock.



Have you ever had an electric shock? While it is an unpleasant experience, it is not usually fatal. However, given the right conditions, the same shock could be fatal! If your body makes a solid connection to the ground, the shock could easily kill you. Here are two examples of a solid ground connection:

- If you are physically standing or touching the ground outside
- ere do or

human body

completes circuit

Appliance with

GFCI

a short

a path to ground

(water faucet)

 If you touch something conductive, such as any part of the plumbing system in your house, that is also touching the ground outside

In other words, if you decide to operate your hedge trimmer in your bare feet and you get a shock, you may not survive it.

How Can a GFCI Help?

A GFCI is a special electrical outlet that prevents electric shocks in situations such as the ones described above. The GFCI monitors the electrical current leaving from and returning to the outlet. The current leaving the outlet should be the same amount as the returning current. If the current returning is less than that which leaves, the missing current could be passing through somebody's body to the ground. The GFCI detects the mismatch and shuts off the electrical outlet in a split second.

Where Should GFCI Outlets Be Located?

GFCI outlets should be installed in any area that presents a risk of an electric shock withg a direct path to the ground. In other words, anywhere you might directly touch the ground outside or anywhere where you might touch a part of the plumbing system. Some smart GFCIs locations are:

- Exterior outlets
- Kitchen counter outlets (not common in Canada)
- Bathroom outlets
- Garage outlets
- Outlets in unfinished basements





©2007 Pillar To Post Inc.

This is not a complete list. Areas near swimming pools, hot tubs, and so on should also include this type of outlet.

GFCIs are not perfect, however, and have been known to "nuisance trip" when connected to certain types of electrical equipment. For this reason, exceptions to the suggested (or required) locations for GFCIs exist. For example, a regular outlet would be a better choice for a freezer in your garage since the potential for nuisance tripping of the GCFI is high and might go undetected for days, leading to spoiled food in the shut-off freezer.

Remote GFC


Several electrical outlets usually connect to a single circuit in an average home. A single GFCI outlet will protect all of the outlets in the circuit, even if the other outlets are not GFCIs. But the GFCI outlet must be the first outlet in the string in order for it to properly protect the other outlets, and, of course the connections have to be properly made.

Remote GFCIs sometimes cause confusion for home owners in the following ways:

- A home owner thinks the bathroom does not have a GFCI because the outlet looks like a standard one. The standard outlet under the protection of a remote GFCI should have a sticker indicating its GFCI protection. The problem is, the sticker does not stick forever. A Pillar To Post® inspector can test this for you.
- A standard outlet that does not appear to work in a bathroom or kitchen may actually be attached to a remote GFCI outlet that has nuisance tripped. Before calling an electrician, check the GFCI outlets in other bathrooms and in other locations around the house.

Testing

GFCIs are easy to test and should be tested every month. Simply press the test button on the outlet. You should hear a pop as the reset button pops out a little. To reset, just press the reset button. If the GFCI fails to trip, or if you are unable to reset it, it is time for an electrician to replace it.




Special breakers also provide GFCI protection to the entire circuit. These breakers can be installed instead of GFCI outlets. The GFCI breaker should also be tested monthly. You will recognize this breaker from the test and reset button.

GFCIs can help prevent injury and death from electric shock. It is a small device worth having to ensure the safety of your family members.

Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

Electrical Outlet Problems

The electrical outlet not only provides vital access to the electrical current that makes your house hum, but it also warrants deeper consideration for reasons of comfort and safety. Our Pillar To Post® inspectors have seen it all when it comes to incorrect outlet wiring, a safety hazard if left unattended. But before we discuss safety measures, let's start with a quick tour of this component and its mate, the plug.



Have you ever wondered why your electrical outlets have holes of different sizes and shape? To accommodate the plug is the obvious answer. But there is more to this relationship than meets the eye. Hidden behind the outlet is a series of wires that must be properly connected for the outlet's safe functioning. On a modern electrical outlet that accommodates a three-pronged plug, each hole serves a specific purpose: the round hole is for the ground pin on the plug; the small slot takes the small blade on the plug and connects to the "hot" wire in the outlet (the wire that can cause a shock); the large slot takes the large blade and connects to the "neutral" wire in the outlet.

Specific wires have to be connected to the proper terminals for an outlet's safe function. Correct installation is so important that our Pillar To Post® inspectors spot-check outlets with an outlet tester during every inspection.

Reverse Polarity

The large slot and small slot on an electrical outlet, and the different-sized blades on a plug, designate their respective polarizations, and ensure that the plug goes in the outlet only one way, a safety feature that reduces the chances of shock. For instance, a light-bulb socket has exposed electrical connections, the threads being the most exposed part. But polarized socket threads are attached to the neutral wire to prevent someone from getting a shock when changing a light bulb.

If the electrical outlet itself is mis-wired with reverse polarity, the lamp socket threads described above will become "hot". If you touch the threads in the socket, or on the bulb as you screw it into the socket, you may get a shock.





©2007 Pillar To Post Inc.

Outlet Not Grounded

Pillar To Post® inspectors have also discovered outlets with the circular ground holes but with no ground wire connected. In older homes, sometimes the cable leading to the outlet does not have a ground wire, yet the outlet has nonetheless been upgraded to a modern grounded type. Some plug-in electrical devices need this ground connection for their built-in safety features. If the outlet appears to be grounded but is not, the device's safety features will not work.


Old Outlets

In older homes some outlets may have no ground slot at all. This does not represent a defect or safety concern, but you will not be able to plug in an electrical appliance that has a ground pin on the plug. Today, most plug-in appliances are not the grounded style and, therefore, do not use or have a ground pin on the plug because they are a double insulated design. In these cases, the old ungrounded outlet will work fine.

If you think it might be a good idea to simply cut off the ground pin to accommodate an outlet without a ground hole, think again. This procedure is doubly unsafe because it not only bypasses the grounding safety feature, but also it bypasses the polarizing feature since a de-pinned plug can be inserted into the outlet either way.

Easy to Fix

An electrician can fix these outlet problems. Though your outlets may appear as minor considerations in the grand scheme of your home, your understanding and the safe installation of your outlets can prevent serious safety hazards.




Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

Railings and Guards

The CDC (Centers for Disease Control and Injury Prevention) estimates that 40% of all unintentional deaths around the home are due to falls. One in five injuries that require a visit to an emergency room is due to a fall. Over 50% of these are falls that happen at home and most of these are falls from stairs and steps.

Railings and guards are designed to keep people from falling and injuring themselves. There is no doubt that properly installed railings and guards could help to improve these statistics.



A railing is something to grip onto when you go up and down a staircase. A guard is something that keeps you from falling off a staircase, deck or balcony. On a staircase, sometimes the railing doubles as a guard.

Many homes have missing or inappropriate railings and guards. One reason is that older homes did not have the same requirements as we do today. Home owners are not required to upgrade their homes to modern safety standards. If we had to upgrade, everybody would have to renovate their home every year just to keep up.

Pillar To Post home inspectors inspect your home with this in mind. We don't believe people should have to renovate their homes every year. Your railings and guards may be perfectly adequate for the time they were installed. At the same time we are concerned for your safety. We believe the solution is to provide you with information on common safety issues and let you decide if you would like to address the issue as a discretionary upgrade.

Here are a few common issues:

Missing railings: Sometimes a staircase has no railing at all, either because the previous owner removed it to make more room to move furniture up the stairs or because it was never installed in the first place. Ideally there should be a railing on any staircase that has more than two or three risers. The actual requirement depends on your area and when the home was built.

Missing guard: A common scenario is there is no guard on an open staircase to a





©2007 Pillar To Post Inc.


basement. In many areas, a guard was not required as long as there was a wall on one side and the basement unfinished. Today, many home owners have turned their basement into a recreation area or a playroom for children. The open staircase is now a danger. Ideally, a railing and guard should be added.

Guard too low: In some cases, an old home will have very low guards on staircases or balconies. This was the design at the time the home was built. Ideally, a guard should be 36 inches high, unless it's part of a staircase handrail in which case 34 inches would be ideal. In many areas, if the drop is six feet or more, a guard of 42 inches is required.

Railing or guard has large openings: Railings and guards may have vertical spindles (called balusters). These keep people from falling through. In some cases, the spacing between the spindles is so wide that a child could fall through. The requirements have changed over the years and also vary from area to area but most authorities believe that a maximum opening of four inches offers the best protection.

Other things to look for:

- Guards that incorporate climbable elements are not ideal. An example is a bench built into a guard or horizontal slats between the spindles on the guard. The concern is that children can climb them and fall over.
- Appropriate lighting for a staircase is a must. A dark stairwell is dangerous. That's all there is to it.
- Uneven stairs and stairs with non-uniform riser height are dangerous.



Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

Carbon Monoxide

Carbon monoxide, or CO, a byproduct of incomplete combustion of fossil fuels, is a colorless, odorless gas. Breathing CO reduces the blood's ability to carry oxygen. In severe cases, CO can cause death.

Defective or malfunctioning fossil fuel appliances, or inappropriate use of appliances that burn fossil fuel close to or inside the home can pose a serious health hazard. Here are a few examples of dangerous operations:

- Running an automobile or gas lawn mower inside the garage
- Operating a barbeque inside the home
- A gas or oil burning furnace with a blockage in the chimney
- Kerosene space heaters
- Operating a generator in the home during a power failure

Symptoms of Carbon Monoxide Poisoning

Symptoms of carbon monoxide poisoning include headache, dizziness, nausea, vomiting, weakness, chest pain, confusion, and loss of consciousness. Carbon monoxide poisoning can lead to death. Low level poisoning may go unnoticed because it may be mistaken for the flu.

Carbon Monoxide Detector

You should have at least one carbon monoxide detector in your home. In some geographic areas, a CO detector is required by law. The CO detector should be placed where you can hear it if it goes off when you are asleep. A CO detector does not have to be placed on the ceiling, since unlike smoke, CO has approximately the same weight as air so it mixes

Information Series



Receptacle




©2007 Pillar To Post Inc.

uniformly throughout the room rather than floating up to the ceiling. To avoid false alarms, do not install the detector next to heating and cooking appliances, vents, flues, or chimneys. Make sure you read and follow the operating, placement, and testing instructions that come with the detector.

If the carbon monoxide detector alarms, take it seriously.

Avoiding CO Poisoning

- Have your heating systems serviced every year by a qualified technician.
- Have your fireplace chimney cleaned and inspected every year.
- Install at least one CO detector in your home and replace the batteries twice per year.
- Open the garage door prior to starting your car; drive the car out promptly. Do not leave it idling in the garage. Do not use a remote car starter when the car is in the garage.
- Do not use a charcoal or propane barbeque in the home.



Pillar To Post®, the home of home inspection

We welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com

HOT WATER ON DEMAND

Imagine a touch-screen pad next to your tub. Enter a desired temperature and the tub fills with water at exactly that temperature. Imagine never running out of hot water again. Welcome to hot water on demand water heaters. There is more to hot water on demand water heaters than endless hot water. They save energy too.

The concept is not new. In fact, these systems have been around for over 40 years and are common where the cost of energy is high such as Europe and Japan.



How It Works

A standard hot water heater heats a large reservoir of water over a long period of time. When you need hot water, it's there waiting for you. Once you use it up, you have to wait if you want more. A hot water on demand system heats water as you need it using gas or electricity. When you turn on a hot water tap:

- 1. Cold water flows into the system triggering the flow sensor
- 2. Powerful burners ignite and heat the water as it flows through the heat exchanger
- 3. The water comes out at the required temperature.

There is no tank or reservoir of water to heat up. For this reason, a hot water on demand system is commonly called a "tankless water heater".

Tank Versus Tankless

When your hot water heater gets old should you replace it with another standard system or should you install a hot water on demand system?

There are three key benefits of a hot water on demand system:

- All the hot water you want.
- More energy efficient because there are no standby heat losses. Standard systems use energy to maintain the water temperature.
- A hot water on demand system is a small box mounted on the wall. Find some extra floor space by removing your old hot water tank.

The main down sides are:

• The up-front costs are much higher, including purchase price and installation costs.





141126-115

- It takes an experienced technician to select and install a system properly. There are lots of ways to go wrong with a hot water on demand system.
- If your power goes out, you don't get any hot water. With a tank system, at least you have a tank full of hot water.

Saving Energy

A hot water on demand system is energy efficient because there is no reservoir of water to keep hot. The **operating efficiency** is not a good measure when comparing a standard system and a tankless system because it does not account for the standby losses. A better point of comparison is the is the **energy factor**. The energy factor is an estimate of the total energy cost for hot water. For example, the energy factor for a typical tank style hot water heater is about 0.55. This means that on average, for every dollar you spend on gas you get about 55 cents worth of hot water. A modern gas fired tankless system has an energy factor of about 0.84.

Saving Money

You can save energy with a hot water on demand system but can you save money? Is the higher upfront cost justified by the energy savings. Most product literature is misleading. A 20% energy saving is a realistic comparison of a modern tank system and a modern tankless system. Depending on your energy cost and the amount of hot water you use in a year, the payback may be 4 to 9 years. This is not bad when you consider that these systems last about 20 years compared to about 10 years for a standard tank hot water heater. If you are planning to live in your house for a while, you will eventually benefit from a lower life-cycle cost and from lower energy costs.

Skilled Technician

Thinking of installing a hot water on demand system? A skilled and experience technician is a must!

A hot water on demand system requires a powerful burner to heat the water as it flows past the flame. The burner has to be powerful enough to heat the water even if several hot water taps are running at the same time. A skilled technician will know how to size the unit to supply the needs of the home. Many less skilled installers get this wrong. You have to consider how cold the water is to start with. For example, consider two identical houses, one located in Florida and the other located in Ohio. The home in Ohio will need a much more powerful burner because the water entering the system may be only 45 degrees in the winter!

A skilled installer will be able to anticipate problems such as an inadequate gas line. The burner in a tankless water heater is so powerful it needs a large gas flow rate to feed it. If the existing gas line is not large enough, a new line will have to be installed.



Pillar To Post®, the home of home inspectionWe welcome your comments and suggestions for future Information Series topicsinfo@pillartopost.com1-800-294-5591www.pillartopost.com